


DMX/RDM

- STEP 1: Attach Box to Connector Strip using holes and hardware provided.
STEP 2: Attach provided strain relief to box and run data cable into box.
STEP 3: Make up connections to XLR DMX connector on cover plate.
STEP 4: Attach Cover Plate to Box with two screws provided and tighten clamp on strain relief.



GATEWAY

- STEP 1: Attach Box to Connector Strip using holes and hardware provided.
STEP 2: Attach Box Extension to Box from STEP 1 with two provided screws.
STEP 3: Attach provided strain relief to box and run data cable into box.
STEP 4: Attach Gateway unit for installation and make up required connections (Use instructions provided with the Gateway unit).
STEP 5: Attach Gateway Cover Plate (with Gateway unit attached) to Box with two screws provided and tighten clamp on strain relief.

